

## PCI Bus, 1–8 axes


### DMC-18x0 and DMC-18x2 Series

#### Product Description

The DMC-18x0 and DMC-18x2 Series are PCI bus motion controllers designed for single and multi-axis applications. For low-cost, single axis PCI applications, Galil's DMC-1417 controller is recommended.

While the DMC-18x0 and DMC-18x2 controllers are similar in performance, the Econo DMC-18x2 has a few less features that result in a cost-savings. Eliminated features include five through eight axes of control, optical isolation on inputs, uncommitted analog inputs, dual encoder inputs, and the auxiliary FIFO and DPRAM communication channel.

*PCI Bus Controllers  
(left to right)  
DMC-1880,  
DMC-1840, and  
DMC-1842*



Both controllers incorporate a 32-bit microcomputer and provide advanced features such as PID compensation with velocity and acceleration feedforward, memory with multitasking for simultaneously running up to eight programs, and uncommitted I/O for synchronizing motion with external events. Modes of motion include point-to-point positioning, jogging, linear and circular interpolation, contouring, electronic gearing and ECAM.

Like all Galil controllers, the DMC-18x0 and DMC-18x2 controllers use a simple, English-like command language which makes them very easy to program. Galil's WSDK servo design software further simplifies system set-up with "one-button" servo tuning and real-time display of position and velocity information.

#### Features

- *PCI card in 1 through 8 axis versions:  
DMC-18x0 where x=1,2,3,4,5,6,7,8 axes  
DMC-18x2 where x=1,2,3,4 axes*
- *User-configurable for stepper or servo motors on any combination of axes. Optional sinusoidal commutation for brushless servo motors. Optional firmware for piezo-ceramic motors.*
- *Accepts up to 12 MHz encoder frequencies for servos. Outputs up to 3 MHz for steppers*
- *PID compensation with velocity and acceleration feedforward, integration limits, notch filter and low-pass filter*
- *Modes of motion include jogging, point-to-point positioning, contouring, linear and circular interpolation, electronic gearing and ECAM. Features ellipse scaling, slow-down around corners, infinite segment feed and feedrate override*
- *Over 200 English-like commands including conditional statements and event triggers*
- *Non-volatile memory for programs, variables and arrays. Multitasking for concurrent execution of up to eight programs*
- *Home input and forward and reverse limits accepted for every axis. Optical isolation on the DMC-18x0 only*
- *8 uncommitted inputs and 8 outputs for 1- through 4-axis models, 24 inputs and 16 outputs for 5- through 8-axis models. Optical isolation on the DMC-18x0 only*
- *High speed position latch for each axis and output compare*
- *8 uncommitted analog inputs for the DMC-18x0 only*
- *Dual encoder inputs for the DMC-18x0 only*
- *Expansion for 64 I/O with optional DB-14064 board*
- *100-pin SCSI connectors for each set of 4 axes. ICM-2900/ICM-1900 breaks-out 100-pin cable into screw terminals*
- *AMP-19540 connects to PCI controller with 100-pin cable and provides four amplifiers for 500 W servos*
- *Communication drivers for all current versions of Windows, DOS, QNX, and Linux*
- *CE certified*
- *Custom hardware and firmware options available*

# PCI Bus, 1–8 axes

## DMC-18x0 and DMC-18x2 Series

### Specifications

#### System Processor

- Motorola 32-bit microcomputer

#### Communications Interface

- DMC-18x0: PCI with bi-directional FIFO plus auxiliary FIFO, and DPRAM
- DMC-18x2: PCI with bi-directional FIFO
- 32-bit PCI interface. 64-bit compatible. 5 V/3.3 V

Commands are sent in ASCII. A binary communication mode is also available as a standard feature

#### Modes of Motion:

- Point-to-point positioning
- Position Tracking
- Jogging
- 2D Linear and Circular Interpolation with feedrate override
- Linear Interpolation for up to 8 axes
- Tangential Following
- Helical
- Electronic Gearing with multiple masters and ramp-to-gearing
- Gantry Mode
- Electronic Cam
- Contouring
- Teach and playback

#### Memory

- Program memory size — 1000 lines × 80 characters
- 254 variables
- 8000 array elements in up to 30 arrays

#### Filter

- PID (proportional-integral-derivative) with velocity and acceleration feedforward
- Notch filter and low-pass filter
- Dual-loop control for backlash compensation (DMC-18x0 only)
- Velocity smoothing to minimize jerk
- Integration limits
- Torque limits
- Offset adjustments
- Option for piezo-ceramic motors

#### Kinematic Ranges

- Position: 32 bit ( $\pm 2.15$  billion counts per move; automatic rollover; no limit in jog or vector modes)
- Velocity: Up to 12 million counts/sec for servo motors
- Acceleration: Up to 67 million counts/sec<sup>2</sup>

#### Uncommitted Digital I/O

	DIGITAL INPUTS	DIGITAL OUTPUTS	ANALOG INPUTS
DMC-1810 thru -1840	8	8	8
DMC-1850 thru -1880	24	16	8
DMC-18x2	8	8	0

#### High Speed Position Latch

- Uncommitted inputs 1–4 latch X,Y,Z,W and 9–12 latch E, F, G, H axes (latches within 0.1 microseconds without optoisolation and within 40 microseconds with optoisolation)

#### Dedicated Inputs (per axis)

- Main encoder inputs — Channel A, A-, B, B-, I, I- ( $\pm 12$  V or TTL)
- Dual encoder (for axes configured as servo) — Channel A, A-, B, B- (for DMC-18x0 only)
- Forward and reverse limit inputs — optoisolated on DMC-18x0
- Home input — optoisolated on DMC-18x0
- Selectable high-speed position latch input
- Selectable abort input for each axis

#### Dedicated Outputs (per axis)

- Analog motor command output with 16-bit DAC resolution
- Pulse and direction output for step motors
- PWM output also available for servo amplifiers
- Amplifier enable output
- Error output (per card)
- High-speed position compare output (per card)

#### Minimum Servo Loop Update Time

-FAST<sup>†</sup>

- 1–2 axes: 250  $\mu$ sec      125  $\mu$ sec
- 3–4 axes: 375  $\mu$ sec      250  $\mu$ sec
- 5–6 axes: 500  $\mu$ sec      375  $\mu$ sec
- 7–8 axes: 625  $\mu$ sec      500  $\mu$ sec

#### Maximum Encoder Feedback Rate

- 12 MHz

#### Maximum Stepper Rate

- 3 MHz (Full, half or microstep)

#### Power Requirements

- |             |               |
|-------------|---------------|
| ■ DMC-18x0: | DMC-18x2:     |
| +5V 750 mA  | +5V 750 mA    |
| -12V 40 mA  | -12V 20 mA    |
| +12V 40 mA  | +12V 20 mA    |
|             | +3.3V 100 mA* |

#### Environmental

- Operating temperature: 0–70° C
- Humidity: 20–95% RH, non-condensing

#### Mechanical

- DMC-18x0: 1–4 axes: 8.175" × 4.2"  
5–8 axes: 12.28" × 4.2"
- DMC-18x2: 7.275" × 4.2"

\* DMC-18x2 revision E and higher require 3.3V from PCI bus.  
Order DMC-18x2-3VREG to have a regulator installed to allow 5V only supply.

<sup>†</sup>Reduced feature set for -FAST.

# PCI Bus, 1–8 axes

## DMC-18x0 and DMC-18x2 Series

### Instruction Set

#### Servo Motor

AF	Analog feedback (18x0 only)
DV	Dual loop operation (18x0 only)
FA	Acceleration feedforward
FV	Velocity feedforward
IL	Integrator limit
IT	Independent time constant
KD	Derivative constant
KI	Integrator constant
KP	Proportional constant
NB	Notch bandwidth
NF	Notch frequency
NZ	Notch zero
OF	Offset
PL	Pole
SH	Servo here
TL	Torque limit
TM	Sample time

#### Stepper Motor

DE	Define encoder position
DP	Define reference position
KS	Stepper motor smoothing
MT	Motor type
QS	Error magnitude
RP	Report commanded position
TD	Step counts output
TP	Tell position of encoder
YA	Step drive resolution
YB	Step motor resolution
YC	Encoder resolution
YR	Error correction
YS	Stepper position maintenance

#### Brushless Motor

BA	Brushless axis
BB	Brushless phase
BC	Brushless calibration
BD	Brushless degrees
BI	Brushless inputs
BM	Brushless modulo
BO	Brushless offset
BS	Brushless setup
BZ	Brushless zero

#### I/O

AL	Arm latch
CB	Clear bit
CO	Configure I/O points
II	Input interrupt
OB	Define output bit
OC	Output compare function
OP	Output port
SB	Set bit
@IN[x]	State of digital input x
@OUT[x]	State of digital output x
@AN[x]	Value of analog input x

#### System Configuration

BN	Burn parameters
BP	Burn program
BV	Burn variables and arrays
CE	Configure encoder type
CN	Configure switches
CO	Configure I/O points
CW	Data adjustment bit
DE	Define dual encoder position
DP	Define position
DR	DPRAM/FIFO update rate
DU	Dual port RAM enable (18x0 only)
DV	Dual velocity (dual loop)
EI	Enable interrupts
EO	Echo off
IT	Independent smoothing
LZ	Leading zeros format
MO	Motor off
MT	Motor type
PF	Position format
QD	Download array
QU	Upload array
RS	Reset
^R^S	Master reset
VF	Variable format

#### Math Functions

@SIN[x]	Sine of x
@COS[x]	Cosine of x
@COM[x]	1's complement of x
@ASIN[x]	Arc sine of x
@ACOS[x]	Arc cosine of x
@ATAN[x]	Arc tangent of x
@ABS[x]	Absolute value of x
@FRAC[x]	Fraction portion of x
@INT[x]	Integer portion of x
@RND[x]	Round of x
@SQR[x]	Square root of x

#### Interrogation

LA	List arrays
LL	List labels
LS	List program
LV	List variables
MG	Message command
QR	Data record
QZ	Return data record
RP	Report command position
RL	Report latch
^R^V	Firmware revision information
SC	Stop code
TB	Tell status
TC	Tell error code

#### Interrogation (cont.)

TD	Tell dual encoder
TE	Tell error
TI	Tell input
TP	Tell position
TR	Trace program
TS	Tell switches
TT	Tell torque
TV	Tell velocity

#### Programming

DA	Deallocate variables/arrays
DL	Download program
DM	Dimension arrays
ED	Edit program
ELSE	Conditional statement
ENDIF	End of cond. statement
EN	End program
HX	Halt execution
IF	If statement
IN	Input variable
JP	Jump
JS	Jump to subroutine
NO	No-operation—for comments
RA	Record array
RC	Record interval
RD	Record data
REM	Remark program
UI	User interrupt
UL	Upload program
ZS	Zero stack
'	Comment

#### Error Control

BL	Backward software limit
ER	Error limit
FL	Forward software limit
OE	Off-on-error function
TL	Torque limit
TW	Timeout for in-position

#### Trippoint

AD	After distance
AI	After input
AM	After motion profiler
AP	After absolute position
AR	After relative distance
AS	At speed
AT	After time
AV	After vector distance
MC	Motion complete
MF	After motion—forward
MR	After motion—reverse
WC	Wait for contour data
WT	Wait for time

#### Independent Motion

AB	Abort motion
AC	Acceleration
BG	Begin motion
DC	Deceleration
FE	Find edge
FI	Find index
HM	Home
IP	Increment position
IT	Smoothing time constant
JG	Jog mode
PA	Position absolute
PR	Position relative
PT	Position tracking
SP	Speed
ST	Stop

#### Contour Mode

CD	Contour data
CM	Contour mode
DT	Contour time interval
WC	Wait for contour data

#### ECAM/Gearing

EA	ECAM master
EB	Enable ECAM
EC	ECAM table index
EG	ECAM go
EM	ECAM cycle
EP	ECAM interval
EQ	Disengage ECAM
ET	ECAM table entry
EW	ECAM widen
GA	Master axis for gearing
GD	Engagement distance for gearing
GM	Gantry mode
GP	Correction for gearing
GR	Gear ratio for gearing

#### Vector/Linear Interpolation

CA	Define vector plane
CR	Circular interpolation move
CS	Clear motion sequence
ES	Ellipse scaling
LE	Linear interpolation end
LI	Linear interpolation segment
LM	Linear interpolation mode
ST	Stop motion
TN	Tangent
VA	Vector acceleration
VD	Vector deceleration
VE	Vector sequence end
VM	Coordinated motion mode
VP	Vector position
VR	Vector speed ratio
VS	Vector speed
VT	Smoothing time constant—vector

# PCI Bus, 1–8 axes

## DMC-18x0 and DMC-18x2 Series

**Connectors** 100-pin, high density; Connector: Amp# 2-178238-9, Cable: Amp# 2-175677-9; Enclosure: Amp# 176793-9

### Axis 1–4 DMC-18x0 and DMC-18x2

1 Analog ground	51 NC
2 Ground	52 Ground
3 5V	53 5V
4 Error output*	54 Limit common
5 Reset*	55 Home W
6 Encoder—compare output	56 Reverse limit W
7 Ground	57 Forward limit W
8 Ground	58 Home Z
9 Motor command W	59 Reverse limit Z
10 Sign W / dir W	60 Forward limit Z
11 PWM W / step W	61 Home Y
12 Motor command Z	62 Reverse limit Y
13 Sign Z / dir Z	63 Forward limit Y
14 PWM Z / step Z	64 Home X
15 Motor command Y	65 Reverse limit X
16 Sign Y / dir Y	66 Forward limit X
17 PWM Y / step Y	67 Ground
18 Motor command X	68 5V
19 Sign X / dir X	69 Input common
20 PWM X / step X	70 Latch X/Input 1
21 Amp enable W	71 Latch Y/Input 2
22 Amp enable Z	72 Latch Z/Input 3
23 Amp enable Y	73 Latch W/Input 4
24 Amp enable X	74 Input 5
25 A+ X	75 Input 6
26 A- X	76 Input 7
27 B+ X	77 Input 8
28 B- X	78 Abort*
29 I+ X	79 Output 1
30 I- X	80 Output 2
31 A+ Y	81 Output 3
32 A- Y	82 Output 4
33 B+ Y	83 Output 5
34 B- Y	84 Output 6
35 I+ Y	85 Output 7
36 I- Y	86 Output 8
37 A+ Z	87 5V
38 A- Z	88 Ground
39 B+ Z	89 Ground
40 B- Z	90 Ground
41 I+ Z	91 Analog in 1†
42 I- Z	92 Analog in 2†
43 A+ W	93 Analog in 3†
44 A- W	94 Analog in 4†
45 B+ W	95 Analog in 5†
46 B- W	96 Analog in 6†
47 I+ W	97 Analog in 7†
48 I- W	98 Analog in 8†
49 +12V	99 -12V
50 +12V	100 -12V

\*Active low

†(NC for 18x2)

### Axis 5–8 DMC-18x0

1 NC	51 NC
2 Ground	52 Ground
3 5V	53 5V
4 Error output*	54 Limit common
5 Reset*	55 Home H
6 Encoder—compare output	56 Reverse limit H
7 Ground	57 Forward limit H
8 Ground	58 Home G
9 Motor command H	59 Reverse limit G
10 Sign H / dir H	60 Forward limit G
11 PWM H / step H	61 Home F
12 Motor command G	62 Reverse limit F
13 Sign G / dir G	63 Forward limit F
14 PWM G / step G	64 Home E
15 Motor command F	65 Reverse limit E
16 Sign F / dir F	66 Forward limit E
17 PWM F / step F	67 Ground
18 Motor command E	68 5V
19 Sign E / dir E	69 Input common
20 PWM E / step E	70 Latch E/Input 9
21 Amp enable H	71 Latch F/Input 10
22 Amp enable G	72 Latch G/Input 11
23 Amp enable F	73 Latch H/Input 12
24 Amp enable E	74 Input 13
25 A+ E	75 Input 14
26 A- E	76 Input 15
27 B+ E	77 Input 16
28 B- E	78 Reserved
29 I+ E	79 Output 9
30 I- E	80 Output 10
31 A+ F	81 Output 11
32 A- F	82 Output 12
33 B+ F	83 Output 13
34 B- F	84 Output 14
35 I+ F	85 Output 15
36 I- F	86 Output 16
37 A+ G	87 5V
38 A- G	88 Ground
39 B+ G	89 Ground
40 B- G	90 Ground
41 I+ G	91 Input 17
42 I- G	92 Input 18
43 A+ H	93 Input 19
44 A- H	94 Input 20
45 B+ H	95 Input 21
46 B- H	96 Input 22
47 I+ H	97 Input 23
48 I- H	98 Input 24
49 +12V	99 -12V
50 +12V	100 -12V

### Auxiliary Encoder (Axis 1–4) DMC 18x0 only

#### 26-pin IDC

1 5V	2 Ground
3 AA+X	4 AA-X
5 AB+X	6 AB-X
7 AA+Y	8 AA-Y
9 AB+Y	10 AB-Y
11 +5V	12 Ground
13 AA+Z	14 AA-Z
15 AB+Z	16 AB-Z
17 AA+W	18 AA-W
19 AB+W	20 AB-W
21 Sample clock	22 NC
23 NC	24 NC
25 NC	26 NC

### Auxiliary Encoder (Axis 5–8) DMC 18x0 only

#### 26-pin IDC

1 5V	2 Ground
3 AA+E	4 AA-E
5 AB+E	6 AB-E
7 AA+F	8 AA-F
9 AB+F	10 AB-F
11 +5V	12 Ground
13 AA+G	14 AA-G
15 AB+G	16 AB-G
17 AA+H	18 AA-H
19 AB+H	20 AB-H
21 Sample clock	22 NC
23 NC	24 NC
25 NC	26 NC

# PCI Bus, 1–8 axes

## DMC-18x0 and DMC-18x2 Series

### Connectors—AMP-19540 Interconnect with four 500 W servo drives

#### J1 Power 8-pin AMP Mate-n-lock II

- 1 Earth
- 2 +VM (18 V–80 V)
- 3 +VM (18 V–80 V)
- 4 +VM (18 V–80 V)
- 5 Ground
- 6 Ground
- 7 Ground
- 8 Ground

#### JX1, JY1, JZ1, JW1 Motor Output 4-pin AMP Mate-n-lock II

- 1 Earth
- 2 A
- 3 C
- 4 B

#### J3 I/O 44-pin Hi-density Female D-sub

- 1 PWM/MCMD Z
- 2 Output 6
- 3 Output 8
- 4 Output 5
- 5 Output 2
- 6 Abort\*
- 7 Input 6
- 8 Latch Z/Input 3
- 9 SIGN/AEN Y
- 10 Encoder compare output
- 11 Reverse limit X
- 12 Reverse limit Y
- 13 Reverse limit Z
- 14 Reverse limit W
- 15 Forward limit W
- 16 SIGN/AEN W
- 17 SIGN/AEN Z
- 18 Output 7
- 19 Output 4
- 20 Output 1
- 21 Output 3
- 22 Input 7
- 23 Latch W/Input 4
- 24 Latch X/Input 1
- 25 PWM/MCMD X
- 26 Home X
- 27 Home Y
- 28 Home Z
- 29 Home W
- 30 Error Output\*/INCOM
- 31 PWM/MCMD W
- 32 5 V
- 33 5 V
- 34 Ground
- 35 Ground
- 36 Input 8
- 37 Input 5
- 38 Latch Y/Input 2
- 39 PWM/MCMD Y
- 40 SIGN/AEN X
- 41 Forward limit X
- 42 Forward limit Y
- 43 Forward limit Z
- 44 Reset\*/LSCOM

#### J4 X-axis 15-pin Hi-density Female D-sub

- 1 I+ X
- 2 B+ X
- 3 A+ X
- 4 AB+ X
- 5 Ground
- 6 I- X
- 7 B- X
- 8 A- X
- 9 AA- X
- 10 Hall A X
- 11 AA+ X
- 12 AB- X
- 13 Hall B X
- 14 Hall C X
- 15 5 V

#### J5 Y-axis 15-pin Hi-density Female D-sub

- 1 I+ Y
- 2 B+ Y
- 3 A+ Y
- 4 AB+ Y
- 5 Ground
- 6 I- Y
- 7 B- Y
- 8 A- Y
- 9 AA- Y
- 10 Hall A Y
- 11 AA+ Y
- 12 AB- Y
- 13 Hall B Y
- 14 Hall C Y
- 15 5 V

#### J6 Z-axis 15-pin Hi-density Female D-sub

- 1 I+ Z
- 2 B+ Z
- 3 A+ Z
- 4 AB+ Z
- 5 Ground
- 6 I- Z
- 7 B- Z
- 8 A- Z
- 9 AA- Z
- 10 Hall A Z
- 11 AA+ Z
- 12 AB- Z
- 13 Hall B Z
- 14 Hall C Z
- 15 5 V

\*Active low

#### J7 W-axis 15-pin Hi-density Female D-sub


- 1 I+ W
- 2 B+ W
- 3 A+ W
- 4 AB+ W
- 5 Ground
- 6 I- W
- 7 B- W
- 8 A- W
- 9 AA- W
- 10 Hall A W
- 11 AA+ W
- 12 AB- W
- 13 Hall B W
- 14 Hall C W
- 15 5 V

#### J11 SPI 9-pin Female D-sub

#### J12 Analog 15-pin Male D-sub (DMC-18x0 only)

- 1 Analog ground
- 2 Analog input 1
- 3 Analog input 3
- 4 Analog input 5
- 5 Analog input 7
- 6 Analog ground
- 7 -12 V
- 8 5 V
- 9 Analog ground
- 10 Analog input 2
- 11 Analog input 4
- 12 Analog input 6
- 13 Analog input 8
- 14 Analog ground
- 15 +12 V

AMP-19540



## PCI Bus, 1–8 axes

### DMC-18x0 and DMC-18x2 Series


#### Hardware Accessories

##### *ICM-1900 Interconnect Module*

The ICM-1900 Interconnect Module breaks-out the 100-pin main cable and 25-pin auxiliary encoder cable into screw-type terminals for quick connection of system hardware. An ICM-1900 is required for each set of four axes. The ICM-1900 is contained in a metal enclosure with dimensions of 13.5" × 2.675" × 6.88" and 1/4" diameter keyholes for mounting. The ICM is normally shipped configured for high amp enable (-HAEN). For low amp enable, order ICM-1900-LAEN. Also specify -OPTO for optoisolated outputs. If using auxiliary encoders with the DMC-18x0, use a CABLE-26-25 26-pin to 25-pin converter to the ICM-1900.



*ICM-1900 Interconnect Module and AMP-1900 Series*



##### *ICM-2900 Interconnect Module*

The ICM-2900 breaks-out the 100-pin SCSI cable into screw-type terminals. One ICM-2900 is required for each set of four axes. The ICM-2900-FL has flanges which allow standard screw-type mounting for card-level Optima controllers. Specify -OPTO for optoisolated outputs. Specify -HAEN for high amp enable and -LAEN for low amp enable. If auxiliary encoders are to be used, use an ICM-2908, a CB-36-25, and a CABLE-36-1M.

*ICM-2900 Interconnect Module with flange*

##### *AMP-19540 Interconnect with Four 500 Watt Servo Drives*

Galil's AMP-19540 is a 4-axis amplifier for driving brush or brushless motors up to 500 Watts each. By interfacing directly to Galil's DMC-18x2 or DMC-18x0 PCI bus controllers, it provides a cost-effective controller/drive solution for multi-axis applications. The AMP-19540 contains four transconductance, PWM amplifiers for driving brush or brushless motors. Each amplifier operates at 18V to 80V DC, up to 7 Amps continuous, 10 Amps peak. The AMP-19540 gain setting is easily configured with jumpers. The PWM switching frequency is 60 kHz. The AMP-19540 enclosure has dimensions of 6.8" × 8.75" × 1". It interfaces to a PCI bus controller with a single, 100-pin high density SCSI cable. Signals for each axis are brought out through D-type connectors located on the AMP-19540. For applications with less than three axes, the AMP-19520 two-axis model is available. A shunt regulator option is also available. CE certified.

##### *DB-14064 I/O Expansion*

The DB-14064 is an optional board which provides 64 additional I/O for the DMC-18x0 and DMC-18x2 controllers. This board mounts directly onto the back of the controller and provides 64 I/O points configurable by the user for inputs or outputs. The I/O is accessible through two 50-pin headers. A CB-50-80 adaptor can be used to convert the IDC connectors to an 80-pin connector. Using the adaptor and the Cable-80 allows for direct connection to the Galil IOM-1964 opto-isolation module.

##### *IOM-1964 I/O Module*

The IOM-1964 is an Input/Output module that provides optical isolation for the 64 extended I/O of the DB-14064. Each of the 64 optically isolated inputs and outputs is rated for 25 mA at up to 28 VDC and is configurable as inputs or outputs in groups of eight bits. The IOM-1964 also provides 16 highside outputs capable of 500 mA of current per output. The dimensions are 7.0" × 13.5". Requires CB-50-80 and CABLE-80.

##### *ICB-99000 Interconnect Converter Board*

The ICB-99000 interconnect converter board provides interconnectivity between Galil's DMC-21x3 amplifier modules and the DMC-18xx controllers. The DMC-21x3 amplifier connects to the 96-pin DIN connector on the ICB-99000, and the DMC-18xx controller connects to the ICB-99000 through the 100-pin SCSI connector. 4.25" × 5.88"

##### *CB-1500 Legacy-to-Optima Converter Board*

The CB-1500 board provides an interconnect solution for upgrading a Legacy series controller (which uses a 60-pin ribbon cable) to a DMC-18xx controller (which uses a 100-pin SCSI cable). The ribbon cables from the Legacy ICM-1100 interconnect modules plug directly into the CB-1500, which then provides a 100-pin SCSI connector for interface to the DMC-18xx. 3.75" × 3.85"

## PCI Bus, 1–8 axes

### DMC-18x0 and DMC-18x2 Series

#### Ordering Information

PART NUMBER	DESCRIPTION	QUANTITY 1	QUANTITY 100
<b>DMC-1810</b>	1-axis Optima, PCI	\$1095	\$ 795
<b>DMC-1820</b>	2-axis Optima, PCI	\$1495	\$ 875
<b>DMC-1830</b>	3-axis Optima, PCI	\$1895	\$ 935
<b>DMC-1840</b>	4-axis Optima, PCI	\$2195	\$ 995
<b>DMC-1850</b>	5-axis Optima, PCI	\$2595	\$1345
<b>DMC-1860</b>	6-axis Optima, PCI	\$2795	\$1425
<b>DMC-1870</b>	7-axis Optima, PCI	\$2995	\$1525
<b>DMC-1880</b>	8-axis Optima, PCI	\$3195	\$1595
<b>DMC-1812</b>	1-axis Econo PCI	\$ 795	\$ 595
<b>DMC-1822</b>	2-axis Econo PCI	\$ 895	\$ 665
<b>DMC-1832</b>	3-axis Econo PCI	\$1045	\$ 725
<b>DMC-1842</b>	4-axis Econo PCI	\$1195	\$ 795
<b>-3VREG</b>	Option for 3 Volt regulator which allows for 5V only supply from PCI bus	No extra charge	
<b>CB-50-100-1880</b>	50- to 100-pin converter board; incl. two ribbon cables for DMC-1850 to -1880	\$ 75	\$ 50
<b>CABLE-26-25</b>	26-pin IDC to 25-pin D type for auxiliary encoders	\$ 15	\$ 15
<b>CABLE-100-1M</b>	100-pin high-density cable in 1 meter length	\$ 125	\$ 95
<b>CABLE-100-2M</b>	100-pin high-density cable in 2-meter length	\$ 135	\$ 100
<b>CABLE-100-4M</b>	100-pin high-density cable in 4 meter length	\$ 150	\$ 105
<b>ICM-1900</b>	Interconnect module (use 1 for every 4 axes). Specify -HAEN for high amp enable or -LAEN for low amp enable	\$ 345	\$ 245
<b>ICM-1900-OPTO</b>	ICM with optoisolated outputs	\$ 395	\$ 295
<b>ICM-2900-FL</b>	Interconnect module (use 1 for every 4 axes). Specify -HAEN for high amp enable or -LAEN for low amp enable. Specify -FL for flange	\$ 295	\$ 195
<b>ICM-2900-OPTO</b>	ICM with optoisolated outputs	\$ 345	\$ 245
<b>AMP-19520</b>	2-axis amplifier for 500 W servos	\$ 595	\$ 395
<b>AMP-19540</b>	4-axis amplifier for 500 W servos	\$ 795	\$ 495
<b>-SR</b>	Shunt regulator option for AMP-195x0	\$ 50	\$ 25
<b>DB-14064</b>	Attachment board for 64 additional I/O for DMC-18x0, DMC-18x2	\$ 295	\$ 195
<b>CB-50-80</b>	50-pin to 80-pin adaptor for DB-14064	\$ 75	\$ 50
<b>IOM-1964</b>	Input/output optoisolated module for 64 I/O	\$ 695	\$ 495
<b>ICB-99000</b>	Interconnect converter board	\$ 75	\$ 50
<b>CB-1500</b>	Legacy-to-Optima converter board	\$ 50	\$ 45
<b>Galil Utilities</b>	Communication drivers, SmartTERM, DMCDOS	\$ 20 for CD; free download	
<b>DMCWIN32</b>	Windows API Tool Kit (VB, C, C++, etc.)	Included with Utilities	
<b>WSDK</b>	Set-up, tuning and analysis software	\$ 195	
<b>ActiveX Tool Kit</b>	Custom ActiveX controls for Visual Basic, Visual C++, etc.	\$ 595	

*Galil offers additional quantity discounts for purchases between 1 and 100. Consult Galil for a quotation.*